

CERTIFICATE

"Certified that the Bldg of Kendriya Vidhyalaya No 2 has been visually inspected and no major structural crack/ distress condition has been observed. However structural stability can be confirmed after structural audit."



Station : Ferozepur Cantt

Dated 31 Aug 2022

(Eradat Ali)  
AE (Civ)  
AGE B/R-II (West)  
Ferozepur Cantt

COUNTERSIGNED




Station : Ferozepur Cantt

Dated 31 Aug 2022

(Rohit)  
Lt Col  
GE (West) Ferozepur Cantt

CERTIFICATE

The Bldg of Kendriya vidhyalaya No 2 has been inspected and no major structural crack/distress condition has been observed. Hence kendriya vidhyalaya school Bldg is structurally safe.



(V Ravindranath, IDSE)  
EE (SG)  
GE (West) Fzr Cantt

Station: Ferozepur Cantt

Dated 10 July 2019